

UNIVERSITY OF RUHUNA

Faculty of Engineering

End-Semester 4 Examination in Engineering: September 2023

Module Number: MN4304

Module Name:

Marine Engineering Knowledge

[Three Hours]

[Answer all questions, Maximum marks: 100, Pass mark: 50]

Instructions to Candidates:

1. Answer any FIVE questions.

- 2. This question paper has SIX questions on four pages.
- 3. Maximum marks allocated for each section of questions are shown.
- 4. Drawings and sketches should be clear, neat and in approximate proportion.
- 5. Use marine colour code for sketches and plans. Red colour is allowed only for sketches.
- 6. Start your answers to each question on a fresh page.
- 7. All questions carry equal marks.
- 8. Clear labelled sketches will be given credits.

Data and Information: Nil

Q1 a) State the factors that may affect the efficiency of air compressors. Explain their Influences over the efficiency.

[06 marks]

b) Explain the necessity of compressed air used onboard ship.

[04 marks]

c) State with reasons the necessity of maintaining bumping clearance of an air compressor.

[04 marks]

- d) If an air compressor fails to unload on starting, one or all of the following could occur. State the correct occurrence and give adequate reasons to support your answer.
 - (i). Compressor would dangerously over speed
 - (ii). Air receiver pressure would be excessively low
 - (iii). Circuit breaker would open on starting
 - (iv). Compressor would pump lube oil

[06 marks]

Q2 a) Sketch and describe the operation of an electrohydraulic type four ram steering gear system.

[08 marks]

b) Distinguish clearly the operation between follow up and non-follow up steering gear systems.

[02 marks]

c) State four main assumptions made in designing an electric steering gear system.

[04 marks]

- d) Sketch and describe a marine tele-motor transmitter, receiver and associated piping [06 marks]
- Q3 a) With reference to transmission line of a ship explain,
 - (i). the Shafting line is angled and the lubricating oil tank is left open to the shaft even at stay.

 [04 marks]
 - (ii). Plummer blocks are of different designs according to their location.

[02 marks]

b) Sketch an oil lubricated stern tube and explain its operation.

[08 marks]

c) What general effects might be continued running at service speed followed by resonance in heavy weather have on marine machinery?

[02 marks]

- d) State the abnormal stresses which may be imposed on:
 - (i) intermediate shafting
 - (ii) tail shafting,
 - (iii) shafting coupling bolts,
 - (iv) thrust shaft

[04 marks]

Q4 a) State the methods of spreading and combating a fire respectively.

[04 marks]

b) Sketch and describe a Soda -Acid type portable fire extinguisher giving suitable chemical reactions caused during operation, indicating operating time, area of coverage and recharging after use.

[08 marks]

c) State the general information indicated on a portable fire extinguisher.

[04 marks]

d) Discuss about the preventive measures to be taken on Class C and Class D fires.

[04 marks]

Q5 a) What general effects might be continued running at service speed followed by resonance in heavy weather have on marine machinery?

[02 marks]

b) (i) Define the phenomenon 'cavitation' followed by reasons to cause it.

[03 marks]

(ii) Distinguish the types of cavitation and locations that they may cause on a Propeller.

[03 marks]

c) With reference to marine piping systems state the application of gland packings.

[04 marks]

b) Discuss the operation of a diesel/heavy fuel oil supply system for two stroke marine diesel engines operating at slow speed, by giving a suitable sketch.

[08 marks]

Q6 a) With reference to deck machinery system installed on a ship explain the operation and construction of a Capstan used for mooring.

[05 marks]

b) Draw timing diagrams to indicate both the 2 stroke and 4 stroke cycle to include all aspects of marine diesel engine operation.

[05 marks]

c) Explain the procedure employed to check deflection of a crank shaft.

[05 marks]

d) State causes for crank shaft deflection

[05 marks]