

CHAPTER 02.	47
Theoretical Background.	47
2.1 Diffraction.	47
2.2 XRD theory of operation.	48
2.2.1 X-ray diffraction.	49
2.3 Bragg's Law.	51
2.4 Miller Indices.....	53
2.5 Scherrer formula.	55
2.5.1 Characteristic Average.	55
2.5.2 Scherrer crystallite size.	56
2.5.3 The method of Warren- Averbach.	56
2.5.4 Crystallite size.	57
2.5.5 Crystallite size distribution.	58
2.5.6 Example.	58
CHAPTER 03.	60
Experimental.	60
3.1.1. Preparation of layers of copper compounds on conductive glass plate.	60
3.1.2 Preparation of layers of zinc compounds on conductive glass plate.....	62
3.2.1 Measuring the resistance of sputtered CuO thin films without CO ₂ and with CO ₂ gas at different temperatures.	63
3.2.2 Measuring the resistance of sputtered ZnO thin films without CO ₂ and with CO ₂ gas at different temperatures.	64
3.3. Measuring the resistance of sputtered CuO and ZnO thin films with N ₂ gas.	64
3.4. Determination of the structure of sputtered CuO and ZnO thin films	65

3.4.1. Siemens D500 Diffractometer.	65
3.4.2. Mounting the sample in the holder.....	66
3.4.3. Scanning process.....	68
3.5. Readings.....	69
3.5.1. Resistance of sputtered CuO thin films versus temperature in CO ₂ gas.....	69
3.5.2 Resistance at room temperature in CO ₂ gas versus time for sputtered CuO thin films.....	70
3.5.3. Resistance of sputtered ZnO thin films versus temperature in CO ₂ gas	72
3.5.4. Resistance of sputtered CuO thin films versus temperature in N ₂ gas.....	73
3.5.5. Resistance at room temperature in N ₂ gas versus time for sputtered CuO thin films.....	74
3.5.6. Resistance of sputtered ZnO thin films versus temperature in N ₂ gas.....	75
CHAPTER 04.....	76
Calculations.....	76
4.1. Gas sensitivity of the sputtered CuO & ZnO thin films.....	76
4.2. Crystallite sizes of some CuO samples.....	79
CHAPTER 05.....	80
Result and Discussion.....	80
5.1. Effect of sputtering conditions on the gas sensitivity of CuO thin films	80
5.2. Gas sensitivity of ZnO thin films.....	88
5.3. Conclusion.....	93
References.....	95